

CHANGE HISTORY for

✓ AVIC-F500BT

Ver. 2.007000

- Solved problem on Polish on-screen keyboard
- Solved reboot problem after receiving specific TMC data in Germany (area information is displayed correctly)
- Improvement of system stability.

Ver. 2.005000

- Solved reboot problem after receiving specific TMC data in Germany

Ver. 2.001000

- Reduction in Cold Boot Time
- Improved Touch Panel Response
- Support for Phonebook Tags (Home - Work - Office-)in the Contacts menu